SITE INSPECTION REPORT
UNIVERSAL MANUFACTURING COMPANY
WOODINVILLE, WASHINGTON

WAD044038073

Report Prepared By:
Suzanne E. Milham
Washington State Department of Ecology
Preliminary Assessment/Site Inspection Program

April, 1986

USEPA SF 1486524

#### SITE NAME/LOCATION

Universal Manufacturing Company # WAD044038073 144 NE 190th Woodinville, Washington 98072

Section 3, Township 26 North, Willamette Meridian.

Latitude: 47/45/18.0

Longitude: 122/09/24.0

#### INVESTIGATION PARTICIPANTS

Suzanne E. Milham

Washington State Department of Ecology

Hazardous Waste Cleanup Program

(206) 459-6319

Ned C. Therien

Washington State Department of Ecology

Hazardous Waste Cleanup Program

No longer with Ecology

#### PRINCIPAL SITE CONTACT

Mr. Donald Jenkins 14410 NE 190th Street Woodinville, WA 98072 (206) 486-0791

#### DATE OF INSPECTION AND SAMPLING

October 23, 1985

#### INTRODUCTION

Universal Manufacturing Company has been identified from Preliminary Assessment screening as requiring further investigations by the U.S. Environmental Protection Agency (EPA) Region X and the Washington State Department of Ecology (Ecology). This site was scheduled for a site inspection to gather additional information and accurately profile the nature and extent of past waste disposal activity. This site investigation was carried out under the Superfund Multi-Site Cooperative Agreement, Preliminary Assessment/Site Inspection (PA/SI) program. This report summarizes the results of this inspection.

#### TABLE OF CONTENTS

- 1.0 Site Owner/Operator
- 2.0 Site History and Background
- 3.0 Environmental Setting
  - 3.1 Climate
  - 3.2 Geology/Hydrology
  - 3.3 Topography and Drainage
  - 3.4 Groundwater and Surface Water Uses
- 4.0 Methods
- 5.0 Analytical Parameters
  - 5.1 Quality Control/Quality Assurance of Sample Collection
  - 5.2 Laboratory and Data Quality Control/Quality Assurance
- 6.0 Results and Discussion
- 7.0 Conclusions and Recommendations
- 8.0 References
- 9.0 Figures and Tables
  - Appendix A: Sample Analysis Results/Correspondence/Historical Documents
  - Appendix B: EPA Site Inspection Report Form
  - Appendix C: Photographic Documentation
  - Appendix D: Site Inspection Sampling Report
  - Appendix E: Site Inspection Health and Safety Report

#### 1.0 SITE OWNER/OPERATOR

Universal Manufacturing is owned and operated by Mr. Donald Jenkins.

#### 2.0 SITE HISTORY AND BACKGROUND

Universal Manufacturing is an electroplater which produces printed circuit boards and sheet metal products. This facility has been in operation since 1968. Prior to 1975, all process waters, solvents and other liquid wastes were discharged through an unlined lagoon and a septic system. During that time period, there were chronic overflow problems of the septic system drainfield. Process waste water was discharged to the unlined lagoon for settling out of solids, the water then flowed into the septic system. This system used two tanks (these have been removed) which overflowed into a drainfield. This drainfield was saturated when in use and the waste water emerged in the parking lot and then flowed across the street towards Bear Creek. This overflow problem is believed to have continued for several years. The company, since 1975, has been hooked up to the METRO sewer system and has had chronic violations of their discharge permit for copper content. The old waste lagoon was subsequently filled in and paved over and is now located under the process buildings.

#### 3.0 ENVIRONMENTAL SETTING

Universal Manufacturing is in a fairly rural area and is bound on the south side by 190 Street northeast and on the west by 144th Street. Bear Creek is 1/4 mile to the west. There are approximately 1866 people within a 1 mile radius. There are 2 parks and 2 schools within one mile. There are two factory buildings containing offices and process equipment lines on site which are in a fenced area.

#### 3.1 Climate

The mean annual precipitation for this area is approximately 45 inches. The maximum 2-year, 24-hour rainfall is approximately 6 inches. In July 1984, the daily maximum temperature was approximately  $84^{\circ}F^{1}$  and in January 1984, the lowest average temperature was  $16^{\circ}F$ .

#### 3.2 Geology and Hydrology

There is a shallow aquifer at approximately 30 feet deep. Soils are glacial drift gravel with some lenses of till. The soils around this site are very permeable, allowing rapid infiltration of precipitation. There is standing and flowing water on-site during heavy rainfall periods.

#### 3.3 Topography and Drainage

There are no storm sewers or drains serving the approximate 2 acre site. There is a palustrine emergent marsh and shrub/swamp wetlands 2/3 of a mile to the east of the site. Drainage flows from this direction into an unnamed tributary of Bear Creek which is 1/4 mile to the west. The site is on a slope which receives drainage water from upgradient wetland runoff.

#### 3.4 Groundwater and Surface Water Uses

Drinking water in the area is drawn from groundwater. Well logs indicate wells to be in a shallow 30 - 50 foot deep aquifer. Within 3 miles there are 1,000 people served by domestic wells. This facility receives its drinking water from the city supply system. The nearest well (Drenkel) is 3/4 of a mile north of the site. Bear Creek is 1/4 mile to the west of the site and is a salmonid spawning stream. Bear Creek is used for recreation but is not used for drinking water. There are 47 domestic wells, 1 industrial use and 2 municipal wells within 1 mile. Groundwater most likely flows in the direction of Bear Creek.

#### 4.0 METHODS

The weather was overcast and approximately  $50^{\circ}F$ . There was a slight wind and no rain. The details of this site inspection and the present status of waste storage and handling practices are included in Appendix A - Milham memo to file.

At 10:30 a.m., we met at Universal Manufacturing with Don Chang and Bill Heaton of the King County Health Department. An interview with the site owner, Mr. Jenkins, was conducted and arrangements were made to collect a number of on-site soil samples. Sampling locations were chosen after a site tour and review of the process and storage areas (see Figure 1).

Soil Sample NCT055 was collected first at 12:50 p.m. This location is near 190th Avenue in front of the facility near a willow tree. This sample location was upgradient from the process area and was intended to represent background soil. The sample was taken at a depth of approximately 1-1/2 foot. The soil was dark black and loamy, with many 1-2 inch diameter smooth rocks interspersed.

Soil sample NCT056 was collected on the bank of the parking lot along 144th Avenue. This area may have received overflow from the septic drainfield and the old waste lagoon. Approximately 6" of ornamental bark covered a layer of plastic and the soil. The sample was taken from a depth of approximately 2 feet. The soil was similar in description to that at to location NCT055.

Soil sample NCT057 was collected from behind the main building near the large metal storage tank in an unpaved area. This tank is used to store process wastes; it is unknown if it was filled or empty. The soils were extremely rocky and consisted almost exclusively of smoothed gravel, medium to large rocks and sand. The sample was collected at approximately 2 feet deep. There was a foul hydrogen disulfide smell present in this location, soil pH was measured and appeared normal. This location was chosen in the event that soil contamination from spills while filling this tank had occurred.

Soil sample NCT058 was collected between the two process buildings in a small unpaved area next to the circuit board shop and covered storage area. Split samples were collected from approximately 2-1/2 feet deep. The soil was comprised of wet gravel and sand. At 2-1/2 feet, there was a layer of reddish-orange material, possibly clay. This collection site was chosen because it was the closest unpaved area to the old waste lagoon.

At the end of the day, sample splits were tagged and signed over to the receptionist at Universal Manufacturing.

#### 5.0 ANALYTICAL PARAMETERS

All samples were analyzed for volatile organics, purgeable chlorinated hydrocarbons, priority pollutant metals, and cyanide. A duplicate of sample NCTO58 was taken for quality control and assurance purposes. Procedural transport blanks were maintained for all parameters sampled.

#### 5.1 Quality Control/Quality Assurance of Sample Collection

Stringent quality control and assurance procedures for sample collection were developed in conjunction with the EPA Site Inspection Sampling Guidelines, and training course literature. These procedures are also discussed in detail in the sampling and safety plans which were developed for this site prior to performing the actual inspection (see Appendices D and E). Procedures for documentation, chain of custody, decontamination of samples and personnel, safety, and labeling are included in these plans.

Blind duplicates were made from one sample for each parameter analyzed. The laboratory was not notified which samples were the duplicates. Transfer and transport blanks were prepared by the laboratory and maintained and analyzed for each parameter sampled.

#### 5.2 Laboratory and Data Quality Control/Quality Assurance

The laboratories which performed the sample analysis practiced strict quality control and assurance per EPA standards.

Lauck's Laboratory supplied a surrogate recovery report contained in Appendix A. Surrogate (chemically similar) compounds were utilized in the analysis of volatile organics. Surrogates were added to each sample prior to extraction and analysis to monitor for matrix effects, purging efficiency and sample processing errors. The control limits used by Lauck's represent the 95 percent confidence interval established by their laboratory through repetitive analysis of these sample types.

The Manchester Laboratory used similar quality control and assurance procedures.

All laboratory sample analyses results were reviewed for consistency and accuracy by each member of the PA/SI team and at least one organic chemist before inclusion to this report.

#### 6.0 RESULTS AND DISCUSSION

Complete sample analysis results are contained in Appendix "A".

#### Volatile Organics

Two of the soil samples analyzed for volatile organics showed contamination with trichloroethylene. Sample NCT 057 contained 150 ppb (ug/kg) and samples

NCT058 and 059 which were duplicates contained 340 and 330 ppb Trichloro-ethylene, respectively. Methylene chloride at 64 ppb and acetone at 61 ppb were present in sample NCT058. This contamination is believed to be from laboratory contamination since the duplicate sample (NCT057) didn't contain these same chemicals.

No other volatile organic compounds were identified in the samples.

#### Metals

When compared, the metals analysis values of background sample NCT055 were lower than those from sample NCT058 which had elevations of copper, lead, zinc, nickel, chromium and cadmium above the background soils at this site.

The amounts of metals available in the soil in Sample NCT058 were significantly lower than ten times primary drinking water regulations standards for maximum contaminants in soil. Because the levels of metals available in the soil are low, there is no apparent metals problem present.

#### Cyanide

The levels of cyanide detected in all the samples analyzed was greatly lower than the 200 ug/l standard set for drinking water by EPA under the ambient criteria. The highest amount detected was .5 mg/kg in sample NCT058 which was collected from between the process buildings. Cyanide at these levels does not represent a significant contamination problem.

#### 7.0 CONCLUSIONS AND RECOMMENDATIONS

Sampling analysis documented that soils were contaminated with trichloroethylene in 2 locations; between and behind the process buildings. It is recommended that a complete RCRA inspection be performed to determine if present day operations are responsible for this soil contamination.

Further sampling of downgradient soils and groundwater should be performed to characterize the extent of the contamination present. Because of the permeable soils and shallow groundwater, there is an increased potential that contamination has spread farther than the site boundaries and possibly into the groundwater.

Because the poor chemical storage and handling practices seen on-site during this inspection, it is highly possible that the contamination detected in the surrounding soils is of a current, ongoing nature. Trichloroethylene was found in bulk feedstock form on-site (see Appendix A - Milham memo to file).

Heavy metals were not found to be excessive in the areas where the old waste lagoon and septic field would have leached to. The elevations of heavy metals between the process buildings could also be due to present day operations.

#### 8.0 REFERENCES

- 1. Climatological Data Annual Summary, WA 1984, Vol. 88, #31 National Oceanic and Atmospheric Administration/
- 2. 1984 USEPA Preliminary Assessment Report on Universal Manufacturing.

9.0 FIGURES AND TABLES

#### 9.0 FIGURES AND TABLES





Figure 1. UNIVERSAL MANUFACTURING SITE SAMPLING LOCATIONS, WOODINVILLE, WASHINGTON, 10/23/85.



#### APPENDIX A

Sample Analysis Results/Correspondence/Historical Documents

Ned Therien Remedial Action Division Dept of Ecology Mail Stop PV-11 98504-8711 Subject FILE # Possible RCRA Storage Facility Syew Messman NW Regional Office Universal Manufacturing Dept. of Ecology 4350 - 150 Th Avenue NE 14410 NE 19074 St. Wooding. 1/2 9807 Redmond, WA 98052-5301 Message 23 1985 Suzanne Milhum and I conducted a CERCLA October site Inspection of Universal Manufacturing in Woodinville Mr. Donald Jenkins, He operator, to determine past huzardous substances, A former from circuit board munufacturing mus filled in and A formerly used septic fank which had received the same wask-types as the pand four soil samples neur He waste old drainfield area. A complete in SIGNATURE analyses have During 30 55-gallon drums which appeared four months with caustic **ORIGINATOR:** 

ORIGINATOR'S FOLLOW-UP COPY

RECIPIENT:

RETURN YELLOW COPY IF A REPLY IS NECESSARY

SEND WHITE AND YELLOW COPIES TO RECIPIENT

# Lauces Testing Laboratories, Inc.

## Certificate

940 South Harney St., Seattle. Washington 98108 (206)767-5060

Chemistry Microbiology, and Technical Services

CLIENT Department of Ecology Manchester Laboratory P.O. Box 346 Manchester, WA 98353 LABORATORY NO. 93597

DATE Dec. 4, 1985

P.O. #F000973

REPORT ON SOIL

SAMPLE IDENTIFICATION

TESTS PERFORMED

AND RESULTS:

Submitted 10/23/85 and identified as shown below:

1) #NCTO55 Universal Manufacturing TV.T 10/23 1250p.

2) #NCTO56 Universal Manufacturing TV.T 10/23 2:00

3) #NCTO57 Universal Manufacturing TV.T 10/23 2:20

4) #NCTO58 Universal Manufacturing TV.T 10/23 3:02

5) #NCTO59 Universal Manufacturing TV.T 10/23 3:02

Samples were analyzed for the volatile fraction of the priority pollutants in accordance with <u>Test Methods for Evaluating Solid Waste</u> (SW-846), U.S.E.P.A., 1982, Method 8240.

#### parts per billion (ug/kg), as received basis

Volatile Organics (by GC/MS)	1	2	3	4	5	Method Blank
Chloromethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Bromomethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Vinyl Chloride	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Chloroethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Methylene Chloride	Trace	Trace	Trace	61.	Trace	L/5.
Acrolein	L/50.	L/50.	L/50.	L/50.	L/50.	L/50.
*Acetone	Trace	Trace	Trace	64.	L/5.	Trace
Acrylonitrile	L/50.	L/50.	L/50.	L/50.	L/50.	L/50.
*Carbon Disulfide	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
1,1-Dichloroethylene	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
1,1-Dichloroethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
trans-1,2-Dichloroethylene	L/5.	L/5.	Trace	L/5.	L/5.	L/5.
Chloroform	Trace	L/5.	L/5.	Trace	L/5.	L/5.
2-Butanone	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
1,2-Dichloroethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
1,1,1-Trichloroethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
*Vinyl Acetate	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Bromodichloromethane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
Carbon Tetrachloride	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
1,2-Dichloropropane	L/5.	L/5.	L/5.	L/5.	L/5.	L/5.
<pre>Trichloroethylene</pre>	L/5.	L/5.	150.	340.	330.	L/5.
This report is submitted for the exclusive use of the person	n, partnership, or co ale of any product or	rporation to whom it is coroceas will be grant	s accressed. Subsequ ed only on contact. T	em use or the name o his company accepts	no responsibility exce	pt

his report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any tember of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except or the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.





Chemistry Microbiology, and Technical Services

PAGE NO. 2

Department of Ecology

LABORATORY NO. 93597

#### parts per billion (ug/kg), as received basis

	1	2	3	4	5	Method Blank
Benzene Chlorodibromomethane 1,1,2-Trichloroethane 2-Chloroethyl vinyl ether Bromoform *4-Methyl-2-pentanone *2-Hexanone 1,1,2,2-Tetrachloroethane Tetrachloroethylene Toluene Chlorobenzene trans-1,3-Dichloropropene Ethylbenzene cis-1,3-Dichloropropene Styrene o-Xylene	L/5. L/5. L/5. L/5. L/5. L/5. L/5. L/5.	L/5. L/5. L/5. L/5. L/5. L/5. L/5. L/5.	L/5. L/5. L/5. L/5. L/5. L/5. L/5. L/5.	L/5. L/5. L/5. L/5. L/5. L/5. Trace L/5. L/5. L/5. L/5.	L/5. L/5. L/5. L/5. L/5. L/5. Trace L/5. L/5. L/5. L/5.	L/5. L/5. L/5. L/5. L/5. L/5. L/5. L/5.

#### Key

\* = Additional compounds from the EPA's Hazardous Substances List. L/ = "less than" trace = an unquantifiable amount between 5-50 parts per billion (ug/L)

#### Comment

Presence of methylene chloride is most likely due to unavoidable laboratory contamination, as this is a common and pervasive laboratory solvent.



his report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any nember of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except or the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.





Chemistry Microbiology, and Technical Services

PAGE NO. 3

LABORATORY NO.

93597

Department of Ecology

Respectfully submitted,

Laucks Testing Laboratories, Inc.

J.M. Owens

JMO:br







Chemistry Microbiology and Technical Services

PAGE NO.

LABORATORY NO. 93597

Department of Ecology

#### **APPENDIX**

### Surrogate Recovery Quality Control Report

Listed below are surrogate (chemically similar) compounds utilized in the analysis of volatile and organic compounds. The surrogates are added to every sample prior e traction and analysis to monitor for matrix effects, purging efficiency, and sample processing errors. The control limits represent the 95% confidence interval established in our laboratory through repetitive analysis of these sample types.

#### parts per billion (ug/kg)

Sample No.	Surrogate Compound	Spike Level	Spike Found	% <u>Recovery</u>	Control Limit
1	d4-1,2-Dichloroethane	62.5	58.0	92.8	50-160
1	d8-Toluene	62.5	72.1	115.	50-160
1	p-Bromofluorobenzene	62.5	56.8	90.8	50-160
2	d4-1,4-Dichloroethane	58.4	54.9	94.0	50-160
2	d8-Toluene	58.4	65.4	112.	50-160
2	p-Bromofluorobenzene	58.4	58.0	99.3	50-160
3	d4-1,4-Dichloroethane	53.5	49.6	92.7	50-160
3	d8-Toluene	53.5	57.8	108.	50-160
3	p-Bromofluorobenzene	53.5	53.3	99.6	50-160







Chemistry, Microbiology, and Technical Services

PAGE NO. 5

Department of Ecology

LABORATORY NO. 93597

### parts per billion (ug/kg)

Sample No.	Surrogate Compound	Spike Level	Spike Found	% Recovery	Control <u>Limit</u>
4 re-inject	d4-1,4-Dichloroethane	243.	233.	95.9	50-160
4 re-inject	d8-Toluene	243.	252.	104.	50-160
4 re-inject	p-Bromofluorobenzene	243.	258.	106.	50-160
5 re-inject	d4-1,4-Dichloroethane	163.	157.	96.3	50-160
5 re-inject	d8-Toluene	163.	172.	106.	50-160
5 re-inject	p-Bromofluorobenzene	163.	175.	107.	50-160
Method Blank	d4-1,4-Dichloroethane	50.	46.4	92.8	50-160
Method Blank	d8-Toluene	50.	51.2	102.	50-160
Method Blank	p-Bromofluorobenzene	50.	51.5	103.	50-160
Method Blank1	d4-1,4-Dichloroethane	50.	46.8	93.6	50-160
Method Blank1	d8-Toluene	50.	50.7	101.	50-160
Method Blank1	p-Bromofluorobenzene	50.	53.6	107.	50-160



 State of
Washington
Department of Ecology
ofEcology

## ENVIRONMENTAL LABORATORY DATA SUMMARY

PROGRAM NUMBER

PAGE	1 of 2
ORIGINA	L TO: LAB FILES
COPIES T	o: 1
Ned	Therien

OFF	Ology	D.F.	ALA SUMMAI
			METALS
W.		1 1	
SOURCE	Universal	Manufacturing	PR:

ORIGINAL TO: LAB FILES COPIES TO:  Ned Therien
868

DATE COLLECTED	-23-8	5 REC	EIVED 10	-24-85	COLLECT	ED BY _	N	ed Theri	eu	·
Sample (Log) Number		Standard	437964 NCT	43796	437966	437967	N.	437964 Duplicate		
	Units	Deviation ± %	NeT	NeT	NCT	NCT 058		Duplicate		
Station:			055	056	057	058				
(C) Dr. 101	us gm		30.4	28.2	36.8	266		30.6		
	0,0									
(2n) D	17		182	282	343	640		181		
Dry wit	Juggm									
Fe										
		<del>                                     </del>								
(Ni) Dry wot	111		33.4	30.6	31.2	77.8		33.2		
Dry 187	14/50			1						
(Cr) Dry 11)	110/20		36.0	16.0	28.0	50.0		30.0		
C sty wi	Jug gor									
Ca Dru (ot	Ug /92	<u></u>	0.19	0.47	0.13	1.19		0.27		
2 3 80 -	100									
(Pb) Della La	111/20		40.5	6.5	0.8	239		1,4		
Ory Wi	Jug gr	1								
Mn		1								
	1	1			,					
SDD. I	uglan	2	0.2	0.3	0.2	0.3		0.3		
Do vig wi	1318									
Be) Dry wt	lya gr	m	2.13	1.39	0.56	0.80		2.12		
(Be) Dry wt	<del>2010.</del>	<u></u>								

NOTE: Dissolved Metals: Those that will pass through a 0.45  $\mu$  membrane filter

Suspended Metals: Those retained by a 0.45  $\mu$  membrane filter

Those found in the unfiltered, rigorously acid digested sample Total Metals:

mg/L= ppm = µg/ml µg/L= ppb = ng/ml

mg/kg = ppm · µg/gm µg/kg = ppb = ng/gm

"<" is "less than" and ">" is "greater than"

# Wrole DATE 2-10-86 Jam arelyDATE 2/10/86

ECY 040-2-32 (a) Rev. 8/81



## **ENVIRONMENTAL LABORATORY DATA SUMMARY**

PAGE	OF
ORIGINAL TO	: LAB FILES
COPIES TO:	

Dej	artmen
Of I	sartmen Ecology
	H STATE OF
(	(10年)
É	

				METAL	,O			
SOURCE Univer	s.l N	1 anufac	turing	-	PROGRA	M NUMBER	898	
DATE COLLECTED 1		<u>5</u> REC	EIVED_lo				Ned Therien	
Sample (Log) Number	Units	Standard Deviation	43 7964 NCT 055	437965	437966	437967	437964 Duplicate	
Station:		Σ %	NCT 055	056	057	058	Papincare	
@ my wot	ug/gm		30.4	28.2	36.8	266	30.6	
					ļ			
Zn	ļ				-			
			<u> </u>					
Fe								
	<del> </del>							
Ni				<del> </del>				
	1		04.5	11.0	1000	50.0	30.0	
Cr Dry wt	Jug gow	\	36.0	16.0	28.0	30.0	30.0	
Cd	<del> </del> -	}	-	<del> </del>				
Cd	<del> </del>		-					
Pb		-	1	1				
		1						
Mn	-							
	+							
- 1. July 1. J								
		<del> </del>						
L							-	

NOTE: Dissolved Metals: Those that will pass throu Suspended Metals: Those retained by a 0.45 Total Metals: Those found in the unfilt	, membrane filter ered, rigorously acid digested sar	mple
mg/L= ppm = /4g/ml /4g/L= ppb = ng/ml	$ma/ka = nom \cdot \mu a/am$	" <" is "less than" and " $>$ " is "greater
ECY 040-2-32 (a)	SUMMARIZED BY	DATE
Rev. 8/81	REVIEWED BY	DATE

State of Washington
Department of Ecology

## ENVIRONMENTAL LABORATORY DATA SUMMARY METALS

PAGE 2 OF 2
ORIGINAL TO: LAB FILES
COPIES TO:
Ned Therien

SOURCE Univer	sul 14	lanutact	uring	<del></del>	PROGRA	AM NUMBER	868			_
DATE COLLECTED 1	0-23-8	S RECE	IVED 10				Ned Theri	en		
Sample (Log) Number	Units	Standard Deviation ± %	437964	43.7965	7966	437967	43 7964	43 7966	7965	
Station:		± %	NCT 055	NCI	NCT 057	NCT 058	Duplicate	Duplicate	Spike	
Hg wet wot	us gm		0.056	0.043	0.019	0.215		0.016	96.7%	ecosely
	0.0								7 10,7	0
(As) Dry wt	ug/gm		75.5	7.5	2.0	10.6	65.5			
0	0.0		١,							
Se Dry wf	ug/gm		1.2	0.5	<0.1	40.1	1.0			
	10.0			<u> </u>						
Ва										
	<u> </u>		·					!		
A Dry wt	ug/gm		0.09	0.09	0.04	0.16	0.10			
7	00			ļ						
Na										

7 Solids
7 G.S. 69.9 92.5 84.8

NOTE: Dissolved Metals: Those that will pass through a 0.45 μ membrane filter

Suspended Metals: Those retained by a 0.45 μ membrane filter

Total Metals: Those found in the unfiltered, rigorously acid digested sample

0.3

0.1

0.2

mg/L= ppm = \(\mu\)g/ml
mg/kg = ppm = \(\mu\)g/gm
\(\mu\)g/kg = ppb = ng/ml
\(\mu\)g/kg = ppb = ng/gm

"<" is "less than" and ">"is "greater than"

SUMMARIZED BY Tyllul u

0.1

DATE 2-10-86

0.2

ECY 040-2-82 (c) Rev. 8/81

Κ

Ca

REVIEWED BY SAME CERRLY

DATE 2/10/86

State of Washington Department of Ecology

## liminary Report

PAGE	· <del></del>	OF	
ORIGINA	LTO: L	AB FI	LES
COPIES T	0:		

	· · · · · · · · · · · · · · · · · · ·	
	ENVIRONMENTAL LABORATORY	COPIES TO:
•	DATA SUMMARY	
	DAIA SUMMARI	
	METALS	•
	MEIAFO	

SOURCE Universal Manufacturing				PROGRAM NUMBER						
DATE COLLECTED 10-23-85 RECEIVED 10-24-85					COLLECTED BY Ned Therien		·			
Sample (Log) Number	Units	Standard Deviation ± %	437964 NCT 055	NC/	43 7966 NC7 057	437967 NOT 058	7964 Duplica	t		
Hg			033	0.56	03 1	0~8		1		$\dagger$
As Dry wt	ug/gm		75.5	7.5	2.0	10.6	65.9	-		-
Se .							·			
Ba										-
				<u> </u>	ļ					$\dagger$
Ag										
										_
Na			ļ							-
			,							+
<u> </u>										+
Ca		·								$\dagger$
									1	$\perp$
								1.	-	+
2 Solids	06		68.8	69.9	92.5	84.8				$\perp$
NOTE: Dissolved Me Suspended M Total Metals: mg/L= ppm = mg/kg = ppm	letals: Ti : Ti =	nose that wil nose retained nose found i	I pass thro d by a 0.4! n the unfi	ough a 0.4!  5 \mu memb  Itered, rigo    " is "le	5 μ memb rane filter prously aci	rane filter d digested and ">" is	"greater than"	DATE	·	
ECY 040-2-82 (c) Rev. 8/81										
Met. O/D1			•							

## State of Washington

#### OLYMPIA ENVIRONMENTAL LABORATORY

**DATA SUMMARY** 

	1		/
E	<i>1</i>	OF	

OR	IGIN	AL	TO:	LAB	FIL	E

COPIES	TO:	m
		 ///

## Tiversal Mfg., upodinville

COLLECTED BY Ned Therien DATE COLLECTED \_ Sample (Log) Number Station: pH (units) Turbidity (NTU) Sp. Conductivity (umhos/cm) COD BOD (5 day) Fecal Coliform (Col./100 ml) NO3-N NO2-N NH3-N T.Kjeldahl-N O-P04-P Total Phos.-P **Total Solids** Total Non Vol. Solids **Total Suspended Solids** Total Non Vol. Sus. Solids 0.2 0.1 0.1 T. Cyanide os Cn

NOTE: All results are in mg/L(ppm) unless otherwise specified. ND is "None Detected" "<" is "Less Than" and ">" is "Greater Than"

ECY 040-2-32 Rev. 9/81



#### STATE OF WASHINGTON

## DEPARTMENT OF ECOLOGY

Mail Stop PV-11 • Olympia, Washington 98504-8711 • (206) 459-6000

Mr. Donald Jenkins Universal Manufacturing Corporation	
14410 N.E. 190th	
Woodinville, WA 98072	
CONSENT FOR ACCES	SS TO PROPERTY
Property Address: 14410 N.E. 190th Woodinville, Washing	gton
I hereby give my consent to officers, acting at the request of the Washington to enter and have access to my proper address for the following purposes:  releases and collect samples	n State Department of Ecology (WDOE) ty located at the above property
Permission for access commences on (through October 25, 1985).	October 23, 1985 and continues
- 80ct 85	Word June
Date	Signature
The WDOE is requested to provide me a at the above property address during the container(s) to receive the duplicate s	ne time of access. I will supply the
8 Oct 85	Signature
The WDOE is <u>not</u> requested to provide collected at the above address during t	me a duplicate of any sample(s)
Date	Signature
Ducc	PIRHOTALE



#### STATE OF WASHINGTON

#### DEPARTMENT OF ECOLOGY

Mail Stop PV-11 • Olympia, Washington 98504-8711 • (206) 459-6000

SAMPLE COLLECTION RECEIPT

_	
Property	Address:

Universal Manufacturing
144 N.E. 190 M Street Woodinville, WA 98072

On this day an officer, employee, contractor, or person acting at the request of the Washington State Department of Ecology (WDOE) collected sample(s) of the following substances from the above property address:

Four samples of soil Numbered NCT-055 south side of sixe NCT-056 west side NCT-054 east side NCT-058 between buildings on cast side

The person who collected the sample(s) offered a duplicate amount of the sample(s) to the owner, operator, or person in charge at the above address who was present at the site on this day.

10/23/85

Ned C. Thomas

Signature of WDOE Representative

10/23/85

Jamas Wills Signature of Site Owner, Operator,

Representative



#### STATE OF WASHINGTON

#### DEPARTMENT OF ECOLOGY

Mail Stop PV-11 • Olympia, Washington 98504-8711 • (206) 459-6000

#### MEMORANDUM

November 5, 1985

TO:

Universal Manufacturing Site File

FROM:

Suzanne Milham

SUBJECT:

PA/SI Site Investigation October 23, 1985

Wednesday, October 23, 1985 (10:30 a.m. - 4:00 p.m.)

Weather: 50°, slight wind, high clouds, overcast, no rain

Personnel: Suzanne Milham, Ned Therien

On Wednesday, October 23, 1985, I, Suzanne Milham, and Ned Therien performed a Site Investigation at the Universal Manufacturing Company, in Woodinville, Washington. This investigation was performed under the Environmental Protection Agency, Multi-Site Cooperative Agreement, Preliminary Assessment Program (PA/SI).

This facility is an electroplater which, prior to 1979, discharged all wastes to a lagoon and septic system. These have since been covered by pavement, a building, and a parking lot.

We arrived at Universal Manufacturing Company at 10:30 a.m. where we were met by Don Chang and Bill Heaton of the King County Health Department. We then conducted an interview and site tour with the company owner, Mr. Jenkins. Ned explained to Mr. Jenkins our purpose and intentions for the days inspection.

Mr. Jenkins said that this site was in a wet area, that there is much surface water flowing on site. The old process discharged wastes into an unlined lagoon for evaporation and sludges were taken to Western Processing Company in Kent. Process water and liquid wastes were discharged into a septic tank system which chronically overflowed from the drain field into the parking lot and street. Mr. Jenkins said that he dug a ditch to help divert water but this didn't prevent septic overflow. This company has discharged between 2000 gallons in 1969 to 8500 gallons per day in 1985 of waste water. This site hooked up to Metro sewers in 1980.

Mr. Jenkins said that very little cyanide was used in plating precious metals. Ferric chloride was the main contaminant that Jenkins said was present in the discharge. Jenkins said that some solvents were used in

File November 5, 1985 Page 2

processing but not in large quantities. Jenkins said that he now leases this site from the "PFG" company and that he sold the property to them a few years ago. Jenkins then took us on a brief site tour.

The appearance of the present day manufacturing process was quite messy. Blue crystals were growing on tanks and pipes, the floor was wet and corrosion was evident in the building. Many full open vats and 55 gallon barrels of materials were stored in several areas on site. Materials in 2 vats were tested with pH paper and exhibited pH of 2 and 12, respectively. A large tank approximately 2500 gallons was present on site in an unpaved area, this tank is believed to be full. Jenkins says this tank is used to temporarily store wastes.

Drums marked solvents, MEK waste, fluoboric acid, nickelaus fluoroborate were seen stored together in a covered paved area. None of the storage areas on site were bermed.

There was a strong chemical smell present in and around the facility and a sweet odor believed to have been cyanide fumes.

We explained to Mr. Jenkins the locations where we would like to take soil samples. Jenkins agreed, and requested split soil samples for his own keeping. Jenkins had no containers for the soil so it was agreed that we would place the samples in zip lock plastic bags.

#### Sampling

Sampling locations can be seen on the attached site sketch.

Sample NCT005 was taken first at 12:50 p.m. This location is near 190th Avenue in front of the facility near a willow tree. This sample is believed to be representative of an upgradient background soil sample. The sample was taken at a depth of approximately 1-1/2 foot. The soil is dark black, loamy, with many 1-2 inch diameter smooth rocks interspersed.

Sample NCT056 was taken on a bank along 144th Avenue. This area may have received overflow from the septic system and is downgradient from the drainfield and old lagoon. Approximately 6" of ornamental bark covered a layer of plastic, soil was dug to approximately 2 feet deep. Soil was rich black loam with small rocks and a layer of clay at approximately 2 feet where the sample was taken.

Sample NCT057 was taken from behind the main building near the large metal storage tank in an unpaved area. The soils were extremely rocky - consisting almost exclusively of smoothed gravel, medium - large rocks, and sand. Soil was dug to approximately 2 feet depth. A foul  ${\rm H_2SO_4}$  smell was present in this hole, the cause is unknown. The pH of the wet soil was measured and appeared normal.

File November 5, 1985 Page 3

Sample NCT058 was taken between the two buildings in a small unpaved area next to the circuit board shop on one side and a covered storage area on the other. Two jars were filled from a depth of approximately 2-1/2 feet deep. The second jar was a duplicate for quality control and assurance purposes. The soil was comprised of wet gravel/rocks and sand. A layer of reddish/orange material, possibly clay, was found at 2-1/2 feet. Because of its unusual appearance, this is where soil was taken for the sample. The air smelled strongly of chemicals here, possibly from the exhaust fans from the buildings which were nearby. The Draeger volumetric air pump and analyzer tube was used, and a faint trace of cyanide was detected in the air.

Sample splits were tagged and given to the receptionist at Universal Manufacturing who signed for them. A full site investigation report will be prepared when sample analyses are completed. Samples will by analyzed for heavy metals, cyanide and volatile organics (VOAS).

The VOA samples were taken to Laucks laboratory immediately after this inspection. Metals and cyanide samples were taken to the Manchester WDOE lab via courier from the Southwest Regional Office.

SM/sr

#### APPENDIX B

EPA Site Investigation Form

	State o		(											1																					SHEET &	<del></del>	*			
O.	partm Ecol	ofo. ran /												757 1			K	l Er	nfo	i. rcei	mei	nt/	Cu	sto	dy.										latilentis	Sa	mplers:	d Ther	ien	
P	roje	ect	Co	de: _	80	68	7533	) -ā	_Ac	cou	nt:_	· · · · · · · · · · · · · · · · · · ·	1,-17				×	Po	) )SS	ible	To	xic	:/H	az	ard	ous	s No	tes:_	A	naly	ze	fo	1	Vo	latile dis	14 <i>11</i> 4,	oli biib <b>213</b> 0	Izanne 1	4:1han	и
Ν	lam	e/l	Loc	atio	րան <b>n:</b>	Uni	ver	sal		Yanu	fa	du	rin	٠,	, siè,			Da	ata	Co	nfi	der	itia	l ,	4. 1.	; [4]	41 n. 	0	190	anic	_ح_				nothign year	₩1.6 - 34	· · · · · · · · · · · · · · · · · · ·	<i>i</i>	3 7 5 7 5 1	
P	roje	ct	Off	icer	: <i>M</i>	ed	The	rie	n		1	J. W.		14. S			, C	D	ata	for	r St	ore	t		y. N		Not						ş, *		A inglinge 17 po 17 ali	Re	corder: 2	lad C.	Then	Men
۲		<del></del>		TRI		#CC	TAC	AINE	RS			LAB		1.	1	TO THE		ATI			T	15.2 m 31. m	ै क्षान र		ATE			<del></del>		OMP					1 1 50 1 00 1 1 1 1 1 1 1 1	1 2 1	STATI	ON	<i>0</i> <sub>82</sub>	<del></del>
I.		-				18	PRE	SER	Υ		NU	JMB	ER		į.		NL	JMB	ER			i serijeri Gladije	i. Ii		1.	•	•	-		DING			T	1,			STATI DESCRIP	TION		
	ξ m		ē	E e	***   : 	8	7 6			•	1	45					3 1	gagara Colo		eare et La La	- 1	أراس	نواها! الراورة دادرة	0.4	. vj				CIVE	טוועם	מא	1 %			nger de s nger de s non all champe de such s	kā Pā	12.			
		201	Wat	Tissue	<u></u>	Unpress	NE S			Yr	Wk	ĸ T	Se	q	1	- 1			or to						Dy	<u> </u>	Time	М	0	Dy	Ti	me	Z.	Frea	Acres of Children	5. ·	ta i History	ad points of		
	18	X			_	X	+		††		$\top$	+	П	<u>.</u>	十		Νc	-7	0	5 9		_	10	_	2 3	П		1	+		<u> </u>		+		South	Sign	1,		<del></del>	
	78	x				Я					$\prod$		П	1				- 7	۵	56	8	5	1				7		1	$\top$	$\top$		T		west s		<del> </del>	nythiatra a		
	48	x				X							П		T		NIC	1	0	5 7	8	5	10	)	23				T		-				east s					
4	19	×				×					$\prod$						N	: 1	0	5/8	3 8	5	10	2	13						1				east s			en buildin	145	
4	79	×				×					$\coprod$						NZ	7	0	59	18	5	1	) 2	3										east		· · · · · · · · · · · · · · · · · · ·	en build		_
			_	. /				Ц.			-	_ _					,   .			4	_ _						$\bot \bot$			$\perp \downarrow$			_		in the second second			AR HARRY ALL AND		
-	$\perp$		$\downarrow$	11	_	<u> </u>	-				$\sqcup$	_ _	1	_	<b> </b> _		$\perp$	Ŀ	100		1		_	$\perp$	$oldsymbol{\perp}$	Ц	_		$\downarrow$	44			_		A. A	NŽ.		atterior de la company		
-	+		-			$\Box$			<b>┤┤</b> -	- -	$\vdash$	4-4	$\vdash$		-		4	+-		- -	1				-	$  \cdot  $		$\dashv$	_	- -			-				eralic	erita en la composición de la composición del composición de la co	<del></del>	
-	+	$\vdash$		+		╁	+		$oxed{\dagger}$		$\vdash \vdash$	+	$\vdash$	-	╀			1 3	10	j	i î	12	1	1	+			1-1		++	-		-		4 <sub>13</sub> +		v	· · · · · · · · · · · · · · · · · · ·		
Ļ	لبل		· · ·	Ш				Ц_		ــــــــــــــــــــــــــــــــــــــ		لــلــ				Ш		بل	لبل						<u>.</u>	ĻΙ	_1_1.						<u>L</u>				Pa	Mariana,	· · · · · · · · · · · · · · · · · · ·	
Г			LA	3		DE	РТН	П	СО	L	QA	\ .	TE	MP	۲.	На	10	CND	СТ	VTY	7	-	,.	М	SCI	ELL	ANEO	US		<b>-</b>				·.··	CHAIN	OF	CUSTODY REC	ORD		
•				BER					MT CE	D	COD	ÞΕ	D	EG C	5.3		ď.	um	ho/	cm	1	ell. Vik		1			1,			Ī				:	Or in thirt					
_	- -	144	.  -		<u>' (                                   </u>		- 1	e its					`	Ŭ					٦,	71 60, 5																	(J. 1913)	table of the state of		
7	Yr	70	K	Se	4	<del>                                     </del>	┯╣	뿌	1	-			-		╀	П	4	T	,	<u> </u>	╀		1				·.			F	RELIN	QUIS	HEC	BY:/:	Signature)		RECEIVED BY: (Sign	atura)	DATE	E/TIME
-	+	$\mid - \mid$	+	++		+	+	$\vdash$	H		+	+	$\vdash \vdash$	i i	-		$\dashv$	1,5	H	+	+			<del>'</del>	<del></del>			<del></del>							Houlen		DEADWED 25	·		,
-	+-		+	++	+-	<b> </b>	+	$\vdash$	H		-	_	$\vdash \vdash$	$\vdash$	+		╁	+	H	+	-									'	KELIN	uuis	nel	) BT:/:	Signature)	j'	RECEIVED BY: (Sign	iture)	DATE	TIME
上	+		$\dashv$	++			+	$\vdash \uparrow$	H	+	-	+-	$\vdash \vdash$	+	T		T	+	H	$\dashv$										 F	RELIN	QUIS	HEC	BY:/:	Signature)		RECEIVED BY: (Signa	sture)	DATE	E/TIME
-	+	<del>  </del> -			-+	╂╼┼╴	+	⊢ -	1		<del>  -</del>					┢			╁╾┨	-+																	e e age			1

RELINQUISHED BY: (Signature) REC'V'D BY MOBILE LAB FOR FIELD ANAL.: (Signature) DATE/TIME DISPATCHED BY: (Signature) DATE/TIME | RECEIVED FOR LAB BY: (Signature) DATE/TIME METHOD OF SHIPMENT Project Officer Copy Yellow Field or Office Copy Pink Laboratory Copy White ECY 040-115

State of Washington	
Department of Ecology	

ECY 040-115

#### FIELD SAMPLE DATA AND CHAIN OF CUSTODY SHEET

The second of th

east side soil near waste storage

William .

Department ( )			L DAIA AND OIL	And of occions (	J11661	
Department of Ecology		₩ Enforcem	ent/Custody		Samplers:	Ned Therien
-	868 Account:	🗵 Possible	Toxic/Hazardous Note	es: Please analyze	for me	Suzanne Milham
Name/Location	: Universal Manufacturing			geable chlorinated	lydricarbons,	
Project Officer:	Ned Therien	Data for	Storet <u>fri</u>	rit, Pollutant Metals, a	nd Cvanide Recorder:	Mod C. Thouse (Signatures Required)
MATRIX	#CONTAINERS LAB & PRESERV. NUMBER	STATION NUMBER	DATE *	COMPOSITE ONLY		TATION CRIPTION
OURCE ODE ov / ater adiment	SS THUNO YEAR	A Magnito (1971)		ENDING DATE		
%	ラゴエ Yr Wk Seq		Yr Mo Dy Time	Mo Dy Time Freq	and the first of the second	· .
48x	X	WC7055	85/023		South side soil	
48 x	X	NCT056	851023		west side soil	near loach field

					****	-s, 2		,	::-	1		; ·							. '										•					-		•				grafia di grafia <del>della</del>
		1	L NUI	AB MB			F1.		EP	-1	S	6	M C	OL TD D	7.00	CC	A DD	E	Ī	DE	ИP G		pł	1				TV /cr				М	IISC	CEL	LAI	NEO	OUS			CHAIN OF CUSTODY RECORD
7	Yr	١	٧k		S	eq	-	·	1	5	Spirit	Typ		*:				i-ee*	ı				-		ľ	· ,				l										RELINQUISHED BY:(Signeture) RECEIVED BY:(Signature) DATE/TIME
													1						L	I		I	Ι		T			ŀ				 				<del></del>				Med C. 21 Dry May
	$\perp$	L	$\perp$		_	L	L	L	L	L	L		L				L	L	L	L		Ŀ			L		Ŀ			L										RELINQUISHED BY: (Signature) RECEIVED BY: (Signature) DATE/TIME
	$\perp$		$\perp$	L			L		L						_		L	L	L	L	L	L	L	L	L	L	L			L		 				-				Mulham Caul fleren 19/4 085
L			_				L	Ŀ	L						L	L	L	Ĺ	-											1	ţ				~;					RECEIVED BY: (Signature) DATE/TIME
L		L					L	L	L				L.									Γ	Γ		Γ	1.								-		,				
																			Γ	1	Γ	Γ	Γ		Γ			1								٠	٠,			REC'V'D BY MOBILE LAB FOR FIELD ANAL.: (Signature)
Г																			Γ					Γ	Γ							 ,	\							
Г		Γ	Τ													1,.			Γ			Γ		Γ	1	Τ				ľ	-	 								DISPATCHED BY: (Signature) DATE/TIME RECEIVED FOR LAB BY: (Signature) DATE/TIME
Г			T									÷.	,	П			Γ		Г	Τ.	Τ	T	T		T							 					<del></del>	·	•	
		T	1					Ī											-		Γ	T	T									 						<del></del>	<u></u>	METHOD OF SHIPMENT

Project Officer Copy

Laboratory Copy

Field or Office Copy

Pink

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

	I. IDENT	IFICATION
1	01 STATE	02 SITE NUMBER D044038073

PART 1 - SITE L	OCATION AND	INSPE	CTION INFORMA	TION			
II. SITE NAME AND LOCATION							
01 SITE NAME, Legal, common, or descriptive name of site)			02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER				
Universal Manufacturing			10 NE <u>190th</u>				
O3 CITY .		04 STATE	05 ZIP CODE	06 COUNTY	07COUNTY 08 CONG CODE DIST		
Woodinville		WA	98072	King			
	TYPE OF OWNERSHI	P (Check o	ne) DERAI	C. STATE D. COUNTY	□ E MUNICIPAL		
LATITUDE LONGITUDE 47 39. 122 08 45".	T F. OTHER _			□ G. UNKNOW	N		
III. INSPECTION INFORMATION							
	3 YEARS OF OPERATI	.968	Present	UNKNOWN			
10,23,85   MONTH DAY YEAR □ INACTIVE		INING YE					
04 AGENCY PERFORMING INSPECTION (Check all that apply)							
□ A. EPA □ B. EPA CONTRACTOR	of termi	☐ C. M	UNICIPAL 🗆 D. MU	INICIPAL CONTRACTOR	(Name of firm)		
L'E STATE OF STATE CONTRACTOR Ecology	e of firm)	□ G. O	THER	(Specify)	<del></del>		
	06 TITLE			07 ORGANIZATION	08 TELEPHONE NO.		
Suzanne Milham	Environme	ental	ist	Ecology	<sup>(</sup> 206 <sup>)</sup> 459-6319		
09 OTHER INSPECTORS	10 TITLE			11 ORGANIZATION	12 TELEPHONE NO.		
Ned Therien	Environme	ental	ist	Ecology	( ) N/A		
					( )		
					( )		
					( )		
					( )		
13 SITE REPRESENTATIVES INTERVIEWED	: 4 TITLE		15ADDRESS		16 TELEPHONE NO		
Mr. Donald Jenkins	Owner		1444 <u>10 NE 1</u> 9	90th Street	206 486-0791		
		,			( )		
					( )		
					( )		
				,			
					( )		
·					( )		
					•		
17 ACCESS GAINED BY 18 TIME OF INSPECTION (Check one)	19 WEATHER COND						
M PERMISSION 10:30 a.m. □ WARRANT	50° part	ial	clearing, va	ariable winds			
IV. INFORMATION AVAILABLE FROM	!				······································		
01 CONTACT	02 OF (Agency/Organi	ization)			03 TELEPHONE NO.		
Suzanne Milham	Washingto	n St	ate Denartme	ent of Ecology	<sup>(</sup> 206 <sup>)</sup> 459-6319		
04 PERSON RESPONSIBLE FOR SITE INSPECTION FORM	G5 AGENCY		RGANIZATION	07 TELEPHONE NO.	08 DATE		
				(224)	1 ,27 ,86		
Suzanne Milham	Ecology	Sta	te	(206) 459-6319	MONTH DAY YEAR		

### GEPA

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 2 - WASTE INFORMATION

I. IDENTIFICATION

II. WASTES	TATES, QUANTITIES, AN	D CHARACTER	ISTICS	, i.e.			
	TATES (Check all that apply)	02 WASTE QUANT	TTY AT SITE	03 WASTE CHARACT	ERISTICS (Check all that i	npply)	
- 4 SOLID	□ E. SLURRY		of waste quantities independent)	X_ A. TOXIC			VOLATUE
E B. POWDE	R, FINES X: F, LIQUID	TONS	Unknown	I x B. CORRO	DSIVE II F. INFEC	TIOUS J. EXPLOS	SIVE
C. SLUDG	E G. GAS	CUBIC YARDS .	Unknown	C. RADIO		MABLE IK. REACT	IVE PATIBLE
D. OTHER	(Specify)	NO. OF DRUMS	Unknown			∭ M. NOT A	
III. WASTE T	YPE	<u> </u>					
CATEGORY	SUBSTANCE N	AME	01 GROSS AMOUNT	G2 UNIT OF MEASURE	03 COMMENTS		
SLU	SLUDGE	·- ··- ·				· · · · · · · · · · · · · · · · · · ·	
OLW	OILY WASTE	<del></del>					
SOL	SOLVENTS		1001/-	1.1.	10/0 /5		
PSD	PESTICIDES		100 gal/m	antn	1968-65 t	o lagoon	
occ	OTHER ORGANIC CH	EMICALS					
100	INORGANIC CHEMIC		11-1	h			
ACD	ACIDS	ALS	Unknown	N/A			<del></del>
			Unknown	N/A	· .		
BAS	BASES		Unknown	N/A			
MES	HEAVY METALS		Unknown	N/A			
	OUS SUBSTANCES (See AP		ly cited CAS Numbers)				
01 CATEGORY	02 SUBSTANCE NA	AME	03 CAS NUMBER	04 STORAGE/DIS	POSAL METHOD	05 CONCENTRATION	06 MEASURE OF CONCENTRATION
Sol	Trichloroethyl	ene					
	*Environmental	Release I	ata*				
	Trichloroethyl	ene		Soil Sampl	l e	340	ppb
	Methylene Chlo	ride		Soil Sampl	l e	61	ppb
		-					
		***************************************					
			1				
		<del></del>					ļ. —
							ļ
V. FEEDSTO	CKS (See Appendix for CAS Numbe	rs)					-
CATEGORY	01 FEEDSTOCK	NAME	02 CAS NUMBER	CATEGORY	· 01 FEEDSTO	OCK NAME	02 CAS NUMBER
FDS		-		FDS			
FDS				FDS			VIII.
FDS				FDS			
FDS			·	FDS			
VI. SOURCES	OF INFORMATION (Cite s	pecific references, e.g.,	state files, sample analysis, i	epons;			
-						· · · · · · · · · · · · · · · · · · ·	
	USEPA 1984 Pre			Report			
	1985 Ecology S	ite insped	ction				

### **SEPA**

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

WA D044038073

. 01 X. A. GROUNDWATER CONTAMINATION 02 ☐ OBSERVED (DATE:) XEXPOTENTIAL ☐ ALLEGED
01 X. A. GROUNDWATER CONTAMINATION 02 - OBSERVED (DATE:
Shallow aquifer is in glacial drift with some lenses of fill. Approximately 1,000
people sewed by domestic wells within three miles. GW at 30 ft. Ecology soil analy-
sis on 10/23/85 show contamination with volatile organics, trichloroethylene, a
crylonitrile and methylene chloride-great potential for aw contemination
01 S. SURFACE WATER CONTAMINATION 02 OBSERVEO(DATE: 1975 ) DOTENTIAL ALLEGED 03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION Waste waters from plating operation ponding above drainfield and draining into
unnamed tributary of Bear Creek. Waste contains cyanide, heavy metals (Pb, Cu)
ammonia etchant. Numerous violations in 1970, no surface water sampling has been
done.
01 © C. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED: 1,500 04 NARRATIVE DESCRIPTION
1,500 residents +300 transients within one mile. A drager tube detected cyanide
contamination in the air, this is believed to have been due to present day operations
01 🗓 D. FIRE/EXPLOSIVE CONDITIONS 02 🗇 OBSERVED (DATE:
03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION
No known or certified fire threat. Fire at plant in 1980 resulted from electrical
sparks; not hazardous materials.
01 □ E. DIRECT CONTACT 02 □ OBSERVED (DATE:)
93 POPULATION POTENTIALLY AFFECTED: <100 04 NARRATIVE DESCRIPTION
The site is partially fenced. There is little potential for direct contact.
the size is partially tenesa. There is little potential for direct contact.
01 X F. CONTAMINATION OF SOIL 02 OBSERVED (DATE:) POTENTIAL ALLEGED 03 AREA POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION
03 AREA POTENTIALLY AFFECTED: 2 04 NARRATIVE DESCRIPTION
O3 AREA POTENTIALLY AFFECTED: $\frac{\langle 2 \rangle}{\langle Acres \rangle}$ O4 NARRATIVE DESCRIPTION  Prior to 1975, wastes were discharged to a septic drainfield and lagoon. Soil
03 AREA POTENTIALLY AFFECTED: 2 04 NARRATIVE DESCRIPTION
O3 AREA POTENTIALLY AFFECTED: <a href="#"></a>
OS AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED:
OS AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED: <a href="#"></a>
O3 AREA POTENTIALLY AFFECTED: <a href="#"></a>
O3 AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED: <a href="#"></a>
O3 AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED:
O3 AREA POTENTIALLY AFFECTED:

SEPA

## POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

WA D044038073

PART 3 - DESCRIPTION OF	TIAZATIDOUS CONDITIONS AND INCIDENTS	·
II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)		
01 XXJ. DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 G OBSERVED (DATE:)	X-X POTENTIAL ALLEGED
Potential damage to flora of Bear	Creek in 1970's from overflow	v of sepic drainfield
and discharge of wastes to Bear C	reek.	
01 K. DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION througe name(s) of species)	02 © OBSERVED (DATE:)	XX POTENTIAL ALLEGED
Potential damage to fauna of Bear	Creek in 1970's from overflow	v of septic drainfield
and discharge of materials to Bea	r Creek.	
01 EXL. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 G OBSERVED (DATE:)	XX POTENTIAL   ALLEGED
None known. Potential for food c		. It is possible
that fish could accumulate heavy	metals.	
01 XXM. UNSTABLE CONTAINMENT OF WASTES (Spills Runoff Standing liquids, Leaking grums)	02 © OBSERVED (DATE: 70,82,85)	☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED:		
Drums stored on unpaved area with in large quantities of drummed an		
1985 inspection.	u tanked waste stored improper	rly on site during
01 □ N. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 🗇 OBSERVED (DATE:)	□ POTENTIAL □ ALLEGED
None Reported		
01 $\mathbb{C}^{\mathbf{X}}$ O. CONTAMINATION OF SEWERS, STORM DRAINS, WW 04 NARRATIVE DESCRIPTION	TPs 02 D OBSERVED (DATE:)	☐ POTENTIAL ☐ ALLEGED
Permitted for 31,000 gpd discharg		
limitations in 1982, discharged c	ontents of acid tank without r	neutralizing it first.
01XXP. ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 X OBSERVED (DATE: 1970's, 82)	□ POTENTIAL □ ALLEGED
Numerous violations of sewer disc		
diverted pleuing rinse water to "	surface waters" when drainfie]	ld was plugged.
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR A		
Ecology sampling showed contamina		
	s now covered by concrete and	a building, there
may be leaching from this lagoon.		•
III. TOTAL POPULATION POTENTIALLY AFFECTED:		
IV. COMMENTS		
Further sampling should be done t		
A RCRA inspection should be done waste storage practices.	at this site to determine and	limit present
V. SOURCES OF INFORMATION (Cre specific references, e.g. state	a files, sample analysis, reports	
Ecology site inspection 10/23/85,		
EPA Preliminary Assessment 1984.	EPA Files, Ecology Fiels, DSHS	i computer files. U.S.

Census 1980; USGS bothess Quad 1973, Geohydro-mono-5; Water Supply Bull. #20.

&EPA

# POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION PART 4 - PERMIT AND DESCRIPTIVE INFORMATION

1.	IDEN	ITIF	CAT	ION
----	------	------	-----	-----

01 STATE 02 SITE NUMBER D044038073

II. PERMIT INFORMATION						
01 TYPE OF PERMIT ISSUED (Cneck all that apply)	02 PERMIT NUMBER	03 DATE IS	SUED	04 EXPIRATION DATE	05 COMMENTS	
A. NPDES						
□ B. UIC				ļ		
□ C. AIR						
© D. RCRA						
□ E. RCRA INTERIM STATUS						
□ F. SPCC PLAN						
IXG. STATE (Specify)	7133	8/29	7/79	8/29/84	Metro pe	rmit sewer
☐ H. LOCAL (Specify)						
☐ 1. OTHER (Specify)						
□ J. NONE						
III. SITE DESCRIPTION			_	<del></del>	·	
	02 AMOUNT 03 UNIT C	F MEASURE	04 TF	REATMENT (Check all that	apply)	05 OTHER
□ A. SURFACE IMPOUNDMENT				-		
B. PILES				INCENERATION UNDERGROUND INJ	ECTION	🖾 A. BUILDINGS ON SITE
X☐ C. DRUMS, ABOVE GROUND				CHEMICAL/PHYSIC		·
🔎 D. TANK, ABOVE GROUND		<del></del>		BIOLOGICAL		
☐ E. TANK, BELOW GROUND			□ E.	WASTE OIL PROCES	SING	06 AREA OF SITE
F. LANDFILL				SOLVENT RECOVER		
☐ G. LANDFARM ☐ H. OPEN DUMP				OTHER RECYCLING	RECOVERY	(Acres)
☐ I. OTHER			⊔ <b>H</b> .	OTHER	ecity)	
Specity) 07 COMMENTS						
A logoon and septic system were used for waste disposal from 1968 - 1975; the facility now is hooked up to METRO sewers. The lagoon has been covered by a building. There are many drums and tanks full of waste chemicals stored on site.						
IV. CONTAINMENT						
01 CONTAINMENT OF WASTES (Check one)						_
☐ A. ADEQUATE, SECURE .	☐ B. MODERATE	□ C. IN	ADEQ	UATE, POOR	x⊒xD. INSECUP	RE, UNSOUND, DANGEROUS
02 DESCRIPTION OF DRUMS, DIKING, LINERS, B	ARRIERS, ETC.					
Site is partially pave	ed and not berm	ed. Th	nere	are wastes	being sto	red in unpaved
areas.						
V. ACCESSIBILITY						·
01 WASTE EASILY ACCESSIBLE: 😾 YES	S 🗆 NO					
02 COMMENTS						
VI. SOURCES OF INFORMATION (Cité so	and the service of the service files some	note entires reco	2015.)			
VI. SOURCES OF INFORMATION (CASSA	eculo reresences, a.g. state mes, san	no.c anarvara, rep.		<u> </u>	<u> </u>	· · · · · · · · · · · · · · · · · · ·
Ecology Site Inspectio	on 10/23/85 and	analys	sis :	results - E	PA ERRIS F	iles

	(C)(C)(D)	7 P
F	a - 153453 .	1.00
18.60	Į.	A starting
No. 12	40.00	F T F

## POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION

	PART 5 - WATER	SITE INSPECT			- ENTAL DAT.	1.1.1	D044038073	s
" SERVING WATER CURRY	PART OF TRAILI	, DEMOGRAFIA	C, AITO LI		ENIAL DAIA	A -		_
II. DRINKING WATER SUPPLY		Г			·	<del></del>		_
01 TYPE OF DRINKING SUPPLY (Check as applicable)		02 STATUS				03	3 DISTANCE TO SITE	
SURFACE	WELL	ENDANGERE			MONITORED			
COMMUNITY A.  NON-COMMUNITY C.	B. □ D. 320	A. □ D. <b>⊠</b>	B.		C. □ F. □	A.	(mi)	
	U. &	· U.E.	L.	<u></u>	F. ⊔	В.	(mi)	_
III. GROUNDWATER  01 GROUNDWATER USE IN VICINITY (Check of								_
A. ONLY SOURCE FOR DRINKING	CXB. DRINKING (Other sources available)	IDUSTRIAL, IRRIGATIO	(Li	OMMERCIAL, mited other source	INDUSTRIAL, IRR ces available)	IIGATION I	D. NOT USED, UNUSEABLE	
02 POPULATION SERVED BY GROUND WAT	ER 1,000	-	03 DISTANC	E TO NEARES	ST DRINKING WAT	TER WELL	3/4(mi)	
04 DEPTH TO GROUNDWATER	05 DIRECTION OF GRO	OUNDWATER FLOW	06 DEPTH TO		07 POTENTIAL		08 SOLE SOURCE AQUIFER	
30 (ft)		ļ	OF CONC	ERN (ft)	OF AQUIFER Unknown		□ YES XĂNO	
09 DESCRIPTION OF WELLS (including useage.	first and location relative to			(11)	Olik liota	(gpd)	<u> </u>	_
The nearest well is 3/4 of a mile to the north of the site; this well is for residential use.								
10 RECHARGE AREA			11 DISCHAR	GE AREA				
☐ YES   COMMENTS			□ YES	COMMENT	S			
□ NO Unknown			₩ NO					
IV. SURFACE WATER			<u></u>					
01 SURFACE WATER USE (Check one)  A. RESERVOIR, RECREATION DRINKING WATER SOURCE		N. ECONOMICALLY IT RESOURCES	□ C. C	OMMERCIA	AL. INDUSTRIAL	. <b>x</b> ī 1	D. NOT CURRENTLY USED	
02 AFFECTED POTENTIALLY AFFECTED BO	DIES OF WATER				•			
NAME:					AFFECT	red	DISTANCE TO SITE	
Bear Creek and its	tributorie:	s			x <del>x.</del>		1/4	
							(mi)	
						· —	(mi)	
V. DEMOGRAPHIC AND PROPERTY	/ INFORMATION							_
01 TOTAL POPULATION WITHIN			·-	02	DISTANCE TO NE	EAREST POPL	JLATION	_
	O (2) MILES OF SITE	c. <u>_ &lt;</u>	6) MILES OF S (4000 10. OF PERSONS	_	·	<1/4	(mi)	
03 NUMBER OF BUILDINGS WITHIN TWO (2)	MILES OF SITE .		04 DISTANCE	E TO NEARES	T OFF-SITE BUILD	DING		
_<2000					<1/4	<u> </u>	mi)	
05 POPULATION WITHIN VICINITY OF SITE (P	Provide narrative description of	nature of population within s	vicinity of site, e.g.	c, rurat vill <b>age</b> , di	ensely populated urb			
This site is in a fa 3 miles.	irly rural a	area, there	are bo	th for	ms and r	esiden	ces within	

SEPA

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

I. IDENTIFICATION

C. \_\_\_\_\_ (mi) D. \_\_\_1

01 STATE 02 SITE NUMBER WA D044038073

PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA VI. ENVIRONMENTAL INFORMATION 01 PERMEABILITY OF UNSATURATED ZONE (Check one) ☐ A. 10<sup>-6</sup> - 10<sup>-8</sup> cm/sec ☐ B. 10<sup>-4</sup> - 10<sup>-6</sup> cm/sec ☐ C. 10<sup>-4</sup> - 10<sup>-3</sup> cm/sec ☐ D. GREATER THAN 10<sup>-3</sup> cm/sec D2 PERMEABILITY OF BEDROCK (Check one) A. IMPERMEABLE (10-4 - 10-6 cm/sec) (Greater than 10<sup>-2</sup> cm/sec) 03 DEPTH TO BEDROCK 04 DEPTH OF CONTAMINATED SOIL ZONE 05 SOIL pH Unknown (ft) 07 ONE YEAR 24 HOUR RAINFALL 06 NET PRECIPITATION 08 SLOPE SITE SLOPE DIRECTION OF SITE SLOPE TERRAIN AVERAGE SLOPE 4.5 SW 09 FLOOD POTENTIAL 10 SITE IS ON BARRIER ISLAND, COASTAL HIGH HAZARD AREA, RIVERINE FLOODWAY SITE IS IN None YEAR FLOODPLAIN 12 DISTANCE TO CRITICAL HABITAT (of endangered species) 11 DISTANCE TO WETLANDS (5 acre minimum) ESTUARINE OTHER \_ (mi) B. \_\_\_\_ \_ (mi) ENDANGERED SPECIES: 13 LAND USE IN VICINITY DISTANCE TO: RESIDENTIAL AREAS: NATIONAL/STATE PARKS. AGRICULTURAL LANDS PRIME AG LAND AG LAND COMMERCIAL/INDUSTRIAL FORESTS, OR WILDLIFE RESERVES

14 DESCRIPTION OF SITE IN RELATION TO SURROUNDING TOPOGRAPHY

<1

The site is on a sloping hillside in a residential, rural industrial area. The site is midway down a hillside with approximately a 20° slope overall. Drainage runs from the top of this hill through the site and into an unnamed tributary of Bear Creek. Bear Creek is approximately 1/2 mile from the site.

B. <1/2 (mi)

VII. SOURCES OF INFORMATION (Cité specific references, e.g., state files, sample analysis, reports)

USEPA, 1984 Preliminary Assessment 10/23/85 Ecology Site Inspection

A B	-000	
F 65	-	
6	-	1 L V

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 6 - SAMPLE AND FIELD INFORMATION

L		IFICATION
01	STATE	02 SITE NUMBER
ì	WA	D044038073

01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	03 ESTIMATED DATE RESULTS AVAILABLE
4	Manchester Environmental Lab	3/86
AKEN		
'S		
	02 IN CUSTODY OF Ecology	
	rName of organization or individua	
IN OF MAPS		
ECTED (Provice narrative des	oripian'	
		,
1		
		•
	AKEN  02 COMMENTS  PS  L  IN OF MAPS  ECTED (Provice narrative des	AKEN  O2 COMMENTS  O2 IN CUSTODY OF Ecology  NOF MAPS  CCTED Gravice harraine gescretion:

VI. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

Ecology Site Inspection 10/23/85, EPA ERRIS Files, EPA 1984 Preliminary Assessment, Geohydo. Mono. 5. Water Supply Bulletin #20.

ACC. STORY STORY, JOS	F	POTE	ENTIAL HAZA	RDOUS WASTE SITE	I. IDENTIF		
	,			CTION REPORT	WA		ENUMBER 44038073
			PART 7 - OWN	ER INFORMATION		00	<del></del>
IL CURRENT OWNER(S)	<del></del>			PARENT COMPANY (It applicable)			
O1 NAME		02 D+	BNUMBER	OB NAME		09 0	+B NUMBER
Donald Jenkins		DO	44038073			]	
OB STREET ADDRESS (P.O. Box. RFD #, etc.)		10	04 SIC CODE	10 STREET ADDRESS: F.O. Box. RFD #, etc.)			11 SIC CODE
14410 NE 190th Street		_	2679				
05 CITY	06 STATE	07 ZI	CODE	12 CITY	13 STATE	142	IP CODE
Woodinville	WA		8072			<u> </u>	v
O1 NAME		02 D-	B NUMBER	OB NAME		09 [	+B NUMBER
D3 STREET ADDRESS (F.O. Box. RFD =, etc.)		1	04 SIC CODE	10 STREET ADDRESS (P.O. Box. RFD #, etc.)			11 SIC CODE
05 CITY	06 STATE	07 ZI	P CODE	12 CITY	13 STATE	142	ZIP CODE
01 NAME	•	02 D	+B NUMBER	08 NAME		09 [	D+B NUMBER
O3 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD #, etc.)			11SIC CODE
05 CITY .	06 STATE	07 Z	P CODE	12 CITY	13 STAT	142	ZIP CODE
O1 NAME		02 D	+B NUMBER	OB NAME		091	D+B NUMBER
03 STREET ADDRESS (F.O. Box, RFD #, etc.)			04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD *, etc.)			11 SIC CODE
G5 CITY :	DE STATE	07 Z	P CODE	12 CITY	13 STAT	14	ŽIP CODE
III. PREVIOUS OWNER(S) (List most recent tirst)				IV. REALTY OWNER(S) (If applicable list most	recent first)		
01 NAME		02 0	+B NUMBER	01 NAME		02	D+B NUMBER
03 STREET ADDRESS (F 0 Bb+ RFD+, etc.)		1	04 SIC CODE	OS STREET ADDRESS (P.O. Box, RED # etc.)		·	04 SIC CODE
05 CITY	06 STATE	07 Z	P CODE	05 CITY	06 STAT	E 07	ZIP CODE
01 NAME		02 D	+B NUMBER	01 NAME		02	D+B NUMBER
03 STREET ADDRESS (P. O. Box, RFD *, etc.)			04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE
ē5 СіТҮ	06 STATE	07 Z	PCODE	05 ÇİTY	06 STAT	E 07	ZIP CODE
C1 NAME		02 0	+B NUMBER	01 NAME		02	D+B NUMBER
03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE	03 STREET ADDRESS (P.O. Box, RFD #, etc.)			04 SIC CODE
OSCITY	06 STATE	07	ZIP CODE	05 CITY	06 STAT	E 07	ZIP CODE
V. SOURCES OF INFORMATION (Cite specif	ic references	i, e.g., s	tate files, sample analysis	, reports)			

USEPA, 1984 Preliminary Assessment.

	PC		RDOUS WASTE SITE	<u> </u>	IFICATION
			TION REPORT	WA	
	·	PART 8 - OPERAT	OR INFORMATION	LWA	D044038073
II. CURRENT OPERATOR (Provide it ditterent t	rom owneri		OPERATOR'S PARENT COMPAN	Y ilt applicable)	
01 NAME		02 D+B NUMBER	10 NAME		11 D+B NUMBER
Universal Manufacturin	g	WAD044038073			
03 STREET ADDRESS (P.C. Box, RFD #, etc.)	· · ·	04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD +, etc.)		13 SIC CODE
14410 NE 190th Street		2679			
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STA	E 16 ZIP CODE
Woodinville	WA	98072			
08 YEARS OF OPERATION 09 NAME OF OWNER	R				
1968-present Donald	Jenkins	•	· ·		
					<del></del>
III. PREVIOUS OPERATOR(S) (List most recent 01 NAME			PREVIOUS OPERATORS' PAREN	T COMPANIES	
J. MANIE		02 D+B NUMBER	10 NAMÉ		11 D+8 NUMBER
3 STREET ADDRESS (P.O. Box. RFD = . etc.)		04 SIC CODE	12 STREET ADDRESS (P.O. Box, RED #, BIC.)		13 SIC CODE
,			TO THEET ADDRESS (F.O. BOX, APD F, BIE.)		13 SIC CODE
5 CITY	06 STATE	07 ZIP CODE	14 CITY	115 STAT	E 16 ZIP CODE
				1.33171	TO ZIP CODE
8 YEARS OF OPERATION   09 NAME OF OWNER	R DURING THIS	PERIOD			
D1 NAME		02 D+B NUMBER	10 NAME	· · · · · · · · · · · · · · · · · · ·	11 D+B NUMBER
•	I				
03 STREET ADDRESS (P.O. Box, RFD #, etc.)		04 SIC CODE	12 STREET ADDRESS (P.O. Box. RFD #, etc.)	<del></del>	13 SIC CODE
			The state of the s		10000000
95 CITY	106 STATE	07 ZIP CODE	14 CITY	I. E STAT	5145710005
			14 611 1	1.55141	E 16 ZIP CODE
B YEARS OF OPERATION   09 NAME OF OWNER	B DUBING THIS	PERIOD			<u></u>
	TO DOTTING THE	T ENIOD			
1 NAME	Т	02 D+B NUMBER	10 NAME		
: Nobe	ŀ	OZ DT B NOWBER	TO NAME		11 D+B NUMBER
3 STREET ADDRESS (P.O. Box, RFD *, etc.)		04 SIC CODE			
O STITLE F ADDRESS (M.O. Box, RFD *, etc.)		04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD #, etc.)		13 SIC CODE
E CITY	100.07.77	27.2.2.2.2			
5 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STAT	E 16 ZIP CODE

USEPA, 1984 Preliminary Assessment Report.

IV. SOURCES OF INFORMATION (Cite specific references, e.g., state lifes, sample enalysis, reports)

	COA	
6		

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 9 - GENERATOR/TRANSPORTER INFORMATION

I. IDENT	IFICATION
01 STATE	02 SITE NUMBER
Inl A	NN44N38N7

L					
II. ON-SITE GENERATOR					
01 NAME		02 D+B NUMBER			
Universal Manufacturing		WAD04403807	13		
C3 STREET ADDRESS (P.O. Box. RFD . etc.)		04 SIC CODE			
14410 NE 190th Street		2679			
05 CITY	06 STATE	07 ZIP CODE			
Woodinville	WA	98072			
III. OFF-SITE GENERATOR(S)					
01 NAME		02 D+B NUMBER	01 NAME		02 D+B NUMBER
None					
C3 STREET ADDRESS (P.C. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (P.O. Box, RF	D#. etc.)	04 SIC CODE
C5 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
01 NAME		02 D+B NUMBER	01 NAME	•	02 D+B NUMBER
03 STREET ADDRESS (P.O. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (P.O. Box, RF	D#, etc.)	04 SIC CODE
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
· ·	ŀ	,			
IV. TRANSPORTER(S)					
O1 NAME		02 D+B NUMBER	01 NAME	1	02 D+B NUMBER
				•	
03 STREET ADDRESS IP.O. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (F.O. Box, RF	D #, etc.)	04 SIC CODE
C5 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
C1 NAME		02 D+B NUMBER	01 NAME		02 D+B NUMBER
C3 STREET ADDRESS (P.O. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (P.O. Box. RF	FD *, etc.)	D4 SIC CODE
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
V COURCES OF INFORMATION			<u> </u>		l

USEPA ERRIS Files WDOE Files

EPA FORM 2070-13 (7-81)

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

I. IDENTIFICATION 01 STATE C2 SITE NUMBER

D044038073 PART 10 - PAST RESPONSE ACTIVITIES II. PAST RESPONSE ACTIVITIES 01 X A WATER SUPPLY CLOSED 02 DATE \_ 03 AGENCY \_ 04 DESCRIPTION 01 & B. TEMPORARY WATER SUPPLY PROVIDED 02 DATE 03 AGENCY 04 DESCRIPTION 01 X C. PERMANENT WATER SUPPLY PROVIDED 02 DATE 03 AGENCY 04 DESCRIPTION 01 😡 D. SPILLED MATERIAL REMOVED 02 DATE 04 DESCRIPTION 01 = E. CONTAMINATED SOIL REMOVED 04 DESCRIPTION 02 DATE 03 AGENCY . Nο 01 F. WASTE REPACKAGED 04 DESCRIPTION 02 DATE 03 AGENCY 01 ☑ G. WASTE DISPOSED ELSEWHERE 03 AGENCY . 02 DATE Some process waste is taken to Arlington Oregon 01 & H. ON SITE BURIAL 04 DESCRIPTION Nο 01 x I. IN SITU CHEMICAL TREATMENT 02 DATE 03 AGENCY 04 DESCRIPTION 02 DATE 03 AGENCÝ 01 DK. IN SITU PHYSICAL TREATMENT 04 DESCRIPTION 02 DATE 03 AGENCY 01 😨 L. ENCAPSULATION 04 DESCRIPTION 02 DATE 03 AGENCY Nο 01 ⊋ M. EMERGENCY WASTE TREATMENT 04 DESCRIPTION 02 DATE 03 AGENCY 01 D N. CUTOFF WALLS 04 DESCRIPTION 02 DATE 03 AGENCY 01 💭 O. EMERGENCY DIKING/SURFACE WATER DIVERSION 04 DESCRIPTION 02 DATE 03 AGENCY 01 T. P. CUTOFF TRENCHES/SUMP 04 DESCRIPTION 02 DATE 03 AGENCY . 01 X Q. SUBSURFACE CUTOFF WALL 02 DATE 03 AGENCY \_ 04 DESCRIPTION

#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

PART 10 - PAST RESPONSE ACTIVITIES

I. IDENTIFICATION 01 STATE 02 SITE NUMBER D044038073

II PAST RESPONSE ACTIVITIES (Continued)		
01 <sup>X</sup> R. BARRIER WALLS CONSTRUCTED 04 DESCRIPTION	02 DATE	03 AGENCY
No		
01 ⅓ S. CAPPING/COVERING 04 DESCRIPTION	02 DATE	03 AGENCY
No		
01 X T. BULK TANKAGE REPAIRED 04 DESCRIPTION	02 DATE	03 AGENCY
No ·		
01 ₩ U. GROUT CURTAIN CONSTRUCTED 04 DESCRIPTION	02 DATE	03 AGENCY
No		
01 및 V. BOTTOM SEALED 04 DESCRIPTION	02 DATE	03 AGEŅCY
No		03 AGENCY
01 D W. GAS CONTROL 04 DESCRIPTION	02 DATE	U3 AGENCY
No		
01 X X. FIRE CONTROL 04 DESCRIPTION	02 DATE	03 AGENCY
No		
01 X Y. LEACHATE TREATMENT 04 DESCRIPTION	02 DATE	03 AGENCY
No		
01 X Z. AREA EVACUATED 04 DESCRIPTION	02 DATE	03 AGENCY
No		OS AGENCY
C1 X: 1. ACCESS TO SITE RESTRICTED 04 DESCRIPTION	G2 DATE	03 AGENCY
No	02 DATE	03 AGENCY
C1 ⊋ 2. POPULATION RELOCATED 04 DESCRIPTION	UZ DATE	03 NGENO1
No. 01 ⊋ 3. OTHER REMEDIAL ACTIVITIES	02 DATE	03 AGENCY
04 DESCRIPTION	UZ DATE	
There have been no remedial activit	iės at this site.	
		•
·		•
·		
III. SOURCES OF INFORMATION (One specific references, e.g., state file	as cample analysis reports)	
III. COCHOLO OF THE OTHER FIRST FOREST CASE COLORS	· ·	
USEPA ERRIS Files		



#### POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER D044038073

II. ENFORCEMENT INFORMATION

01 PAST REGULATORY/ENFORCEMENT ACTION 🙀 YES 🗆 🗆 NO

02 DESCRIPTION OF FEDERAL, STATE, LOCAL REGULATORY/ENFORCEMENT ACTION

METRO has sited Universal Manufacturing on several occasions for exceeding their permit limits on copper in their waste stream. A \$250 penalty was levied by Ecology ordering that Universal Manufacturing stop discharging contaminated water to surface water on the ground. This order also directed them to stop using their septic system drain field for disposal of contaminated materials.

 $\pmb{\text{iII. SOURCES OF INFORMATION}} \ \ \textit{(Cite specific references, e.g., state files, sample analysis, reports)}$ 

USEPA ERRIS Files WDOE NWRO Files, EPA Preliminary Assessment

### APPENDIX C

Photographic Documentation

All photos were taken by Suzanne E. Milham on 10/23/85 using a Canon Sureshot camera with asa 100 film, on automatic light and shutter settings.



NCT058+NCT059 were taken of soil on the east side of the facility between the process buildings near a storm drain.



At approximately 2 feet deep there was an orangish color to the soil. This location was immediatly adjacent to where several open full drums of chemicals were being stored.



Background sample #NCT055 being collected on the South side of the complex by Ned Therien.



Sample NCT056 was taken here on the West side of the complex near where the old septic leach field was located. Ned Therien is seen collecting the sample.



Sample NCT057 was taken near an unpaved waste storage area on the east side of the site. The large storage tank which was full at the time of the

in these photos.

inspection can be clearly seen



Sampling location NCT058+059



Sample NCT057 was taken in this location, the type of sand and gravel soils present can be seen in this photo.



#### APPENDIX D

Site Inspection Sampling Report

## UNIVERSAL MANUFACTURING COMPANY WOODINVILLE, WASHINGTON

SITE INVESTIGATION SAMPLING PLAN

SEPTEMBER 1985

Prepared by

Suzanne E. Milham Washington State Department of Ecology

#### Site Sampling Plan Summary

Site: Uni	versal	Manufacturing	Company
-----------	--------	---------------	---------

144 N.E. 190th Street Woodinville, WA 98072

Section 3, Township 26N, Range 5E, WM

Proposed Date	e of Investigation:	· · · · · · ·
Preparer: Sy	ızanne E. Milham	
Reviewed by:		
-	Project Officer, EPA	Date
Δ ·	Site Inspection Team Leader	Date
	Site Inspection Team Member Health and Safety Coordinator	Date

#### I. INTRODUCTION

The purpose of this plan is to detail the program of site investigation sampling activities to be carried out by the WDOE PA/SI team at Universal Manufacturing Company.

# II. SITE DESCRIPTION AND WASTE CHARACTERISTICS

This facility is an electroplater which, prior to 1975, discharged all process waters, solvents, and other liquid wastes through a lagoon on septic system. The lagoon has since been filled in and the facility now discharges to Metro Sewers. There were chronic problems with septic drainfield overflow when in use. The site is in a rural area near Bear Creek which is used for salmonid spawning. The groundwater which is shallow at a 30 foot depth is utilized by approximately 1000 people within a 3 mile radius. Hazardous wastes at this site include chlorinated solvents, cyanide, acids, heavy metals.

# III. OBJECTIVES

Sampling of groundwater will be carried out to determine if contamination is present. Soil core samples will also be taken. Two well water and four soil samples will be taken. Priority pollutant scans for heavy metals, chlorinated solvents, cyanide, volatile organics, and arises will be done.

# IV. SAMPLE COLLECTION/ANALYSIS PARAMETERS

Two samples of the groundwater will be taken, one at the Drinkel well 3/4 mile north of the site, if possible. This is the nearest downgradient well. A second groundwater sample will be taken from a later identified upgradient background well. Core soil samples will be taken as close to the drainfield and lagoon as possible.

If any leachate is present, it will be sampled as well.

The following table outlines the numbers of samples to be taken and the parameters for which they will be analyzed.

## Sample Information

#### Groundwater Samples

- 1 Drinkel well 3/4 mile
  north of site
- 1 background well

1 - transport blank

1 - leachate if available

## Analysis Parameters

Cyanide Chlorinated solvents Heavy metals

Chromium, copper Lead, zinc palladium Phosphoric acid

· Volatile organics

#### Core Soil Samples

Analysis Parameters

3 - Soil samples around drainfield and lagoon

Cyanide

Heavy metals/

Chromium, copper Lead, sine, palladium

Phosphoric acid

Volatile organics

Paryenble Chlorinatul HC

Sample splits will be 'made available upon request to the site owners.

Equipment List

**EQUIPMENT** 

USE

Sample Containers

Appropriate to analyses desired (see

Table)

Sample Preservatives

See Table

Field Blanks

See Table

Keys

For locked monitoring wells.

Pipe wrenches

May be necessary to remove steel security cap on wells which have not been recently opened and sampled.

Tape measure

Use to measure diameter of well casing above ground level.

Used to determine static water level

and total depth of well.

Pocket Calculator

graduated depth sounder

Use for static water volume

calculations.

Pump

Use to purge or evacuate well prior to obtaining sample; it is not a

recommended means to obtain a sample.

Sampling Trier

Collect soil samples at depths of up

to several feet below surface.

Stainless Steel Mixing Bowl

Electronic water level indicator/

Composite soil samples.

- Stainless Steel Spoons

Soil sample collection.

Teflon Well Bailer

A bailer is a device which is lowered into a well to obtain water samples.

#### EQUIPMENT

USE

Monofilament Line

Use for lowering bailer into well; should be of sufficient strength to hold full bailer and overcome any resistance between well casing and bailer. The use of any other type of line is not recommended. Steel wire might be an appropriate substitute but can cause handling problems for personnel wearing gloves.

Decontamination solutions/water (Methanol)

Use for decontaminating sampling equipment, bailer, and water level indicator between samples.

Plastic pails, graduated

Use for measuring volume of water taken from well prior to sampling.

Thermometer

Use to measure temperature of ground-water.

Field logbook

Used to record field observations.

Camera/film
Sample tags
Chain-of-custody records
Receipt for sample forms
Waterproof ink pen
Compass

Use to document sampling procedure.

# Field Measurements and Observations

The following field measurements and observations will be logged:

- 1) Measure the diameter of the well casings.
- 2) Note the casing materials (i.e., pvc, steel, etc.).
- 3) Available well log information noted.
- 4) Weather conditions, air temperature, sky conditions, etc.
- 5) Physical observable characteristics of water.
- 6) Observations about well characteristics.
- 7) Temperature of water before and after purging.

# Groundwater Sampling Procedures

A clean Teflon bailer will be used to obtain water to fill sample containers. This bailer will be lowered into the well on a mono-filament nylon line. Care will be taken to avoid agitation, which may promote the loss of volatile constituents from the samples.

#### Soil Sampling Procedures

Surface soil will be removed with a shovel to a depth of 24". Soil samples will be collected with a specially cleaned stainless steel sampling trier, trowel or spoon at this level. Soil samples will be composited in pairs by mixing in a stainless steel bowl.

# Decontamination Procedures for Sampling Equipment

After equipment such as the bailer is used for sampling, it will be decontaminated before being used to sample another location. This will prevent cross contamination.

Equipment will first be washed with soap and water solution; then rinsed with clean water.

After this, equipment will be rinsed with methanol and water mixture and then triple rinsed with deionized water and let to air dry.

# Department of Ecology Chain of Custody Procedures

#### Background

These procedures were adopted for use by the Department of Ecology from those used by the EPA Region X Surveillance and Analysis Division. A documented record of sample handling is necessary for special studies involving compliance monitoring or other enforcement-related activities in which the data may be used in litigation. The evidence-gathering portion of a survey is characterized by the minimum number of samples required to give a fair representation of the effluent, or water body, air shed, or other media, from which they are taken.

The procedures described in this section represent the optimum method. The failure in any particular instance to follow one or more steps does not necessarily render evidence either inadmissible or unusable. Consequently, there should be no hesitancy to mention any deviation in procedure in any given case.

# Definition of Custody

Chain of custody procedures are followed to establish sample possession from the time it is taken until the results are introduced as evidence into court. A sample is in your "custody" when:

- 1. It is in your actual physical possession.
- 2. It is in your view, after being in your physical possession.
- 3. It was secure beyond a reasonable doubt if not in your view.

#### Sample Collection

- 1. As few people as possible should handle the sample.
- 2. Preprinted sample tags are filled out in waterproof ink and attached to the sample container at the time the complete sample is collected. The tags contain, as a minimum, the following information: station identification, station location, date-time-type of sample (grab or composite), and initials of the sample collector and any observing witness. It is desirable that witnesses be present.
- 3. Blank samples, using distilled water with preservatives added, may be prepared at the time of sample collection and later analyzed to establish the lack of container or preservative contamination.
- Bound Field Data Record logbooks with numbered pages are used to record field measurements and other pertinent information. These notes may be used to refresh the sampler collector's memory in the event he later takes the stand to testify regarding his actions during the evidence-gathering activity. Data entered in the logbooks are recorded with ballpoint pen or waterproof ink. Each page is signed by the sample collector and any available witnesses. Any errata in making entries should be lined out with a single line and then initialed.
- 5: The sample collector is responsible for the care and custody of the samples until properly dispatched to the receiving laboratory or turned over to an assigned custodian. The sample collector must assure that each container is in his physical possession or in his view at all times, or locked or sealed in such a place and manner that no one can tamper with it.
- 6. If colored slides, photographs, or other related evidence are obtained to show the impact of the pollutant or substantiate any other conclusions of the investigation, the following documentation is required on the back of each photo or in the Field Data Record Logbook: time, date, location of the photographer when taking the photo, film type, and the signature of the photographer and any witnesses.

#### Transfer of Custody and Shipment

Samples are accompanied by a chain of custody record which includes the name of the survey, sample collector's signature, number, and description of the samples. When turning over the possession of a part or all of the samples to a field analysis station or to a laboratory, the transferer and transferee will sign and record the time and date on the sheet.

- 2. All packages are accompanied by the sample custody record showing identification of the contents. The original accompanies the shipment, and a copy is retained by the survey coordinator. The chain of custody record is signed by the sample collector along with recording the date and time. It is then placed inside the shipping container.
- 3. Samples are carefully packed for shipment in suitable containers to avoid damage. The shipping containers are locked for shipment, or sealed in such a manner that the container cannot be opened without breaking the seal. This lock or seal is not removed until the shipping container is opened by the laboratory custodian or one of his alternates.
- 4. If sent by mail, the package is sent via Registered Mail with Return Receipt Requested. If sent by common carrier, all shipping receipts are retained as part of the permanent chain of custody documentation.

# Laboratory Custody Procedures

- 1. Couriers picking up samples at the bus depot, post office, etc., sign and retain the shipping documents to acknowledge receipt of the samples.
- 2. All incoming samples are received only by the laboratory sample custodian or one of his alternates who indicate receipt by signing the chain of custody record accompanying the samples and retaining it as part of the permanent record. Samples are then logged into the laboratory and assigned a laboratory number.
- 3. The sample custodian or one of his alternates is responsible for the security of the samples in the laboratory. Samples are stored in locked or sealed refrigerators or cabinets with the keys to the locks held by the sample custodian or one of his alternates.
- 4. Only the sample custodian or his alternates distribute samples to laboratory personnel who are to perform analyses. Laboratory personnel record in their laboratory notebook or analytical worksheet information describing t sample, the procedures performed and the results of the analyses. The notes shall be retained as a permanent record in the laboratory and should note any abnormalities or other significant observations about the samples or analyses.
- 5. Laboratory personnel are responsible for the care and custody of the sample once it is distributed by the sample custodian.
- 6. Once the sample analyses are completed, the unused portion of the samples, together with all identifying tags and laboratory records, are returned to the sample custodian. The returned tagged sample is retained in locked or sealed cabinets or refrigerators until it is required for trial.
- 7. Analytical results are checked and initialed by senior laboratory personnel. The original lab bench sheets are stored in the laboratory files.

8. Samples and tags are discarded only upon the order of the Laboratory Director, after conferring with appropriate personnel in the Enforcement Division or the Assistant Attorney General handling the case to make certain that these items are no longer needed.

# APPENDIX E

Site Inspection Health and Safety Report

# UNIVERSAL MANUFACTURING COMPANY WOODINVILLE, WASHINGTON

SITE SAFETY AND HEALTH PLAN

SEPTEMBER 1985

Prepared by

Suzanne E. Milham Washington State Department of Ecology

# Site Safety Plan Summary

Site:	Universal Manufacturing	Company
	144 N.E. 190th Street	•
	113431- 114 00070	

Woodinville, WA 98072

Section 3, Township 26N, Range 5E, WM

Preparer: Suzanne E. Milham

Reviewed by:		
	Project Officer, EPA	Date
· ·	Site Inspection Team Leader	Date
	Site Inspection Team Member	Data

Type of Facility: This facility produces circuit boards and sheet metal products, and does electroplating.

Size of Area: 2 acres.

Land Use in Surrounding Area: This site is in a rural area. Bear Creek is 1/4 mile to the west. Groundwater is at 30 feet and is a source of drinking water for up to 1,000 people within a 3 mile radius. There are 2 parks and 2 schools within 1 mile.

Hazard Type: Direct contact, possible respiratory.

Waste Type: Heavy metals including copper, zinc, lead, cyanide compounds, chlorinated solvents.

Identified Wastes: Cu, Pb, Zn, cyanide, trichloroethane, methyl-ethyl ketone, phosphoric acid.

Factors Promoting Action: This inspection is being carried out under the Multi-Site Cooperative Agreement, Preliminary Assessment/Site Investigation Program. This investigation will attempt to identify the presence, location, and spread of hazardous materials at this site.

Sampling Plan: Soil core samples, groundwater well samples, and possible solid waste or sediment samples if a leachate is present.

Levels of Protection: Level D, Level C, if necessary. Professional judgment and analytical detection equipment will be used in determining the adequacy of these protection levels.

Monitoring Equipment: Draeger tubes for cyanide.

Personnel: Inspection Coordinator: Ned Therien

WDOE Team Member: Suzanne Milham, Site Safety Coordinator

EPA Project Officer: Bob Kievit

Personnel Training: The inspection team leader and site safety coordinator have had formal EPA site inspection training as well as emergency first aid and CPR. All unfamiliar on-site activities will be rehearsed prior to the inspection. All team personnel are capable of making professional judgments in hazardous situations. All WDOE site investigation team members are participants in the medical monitoring program.

# Emergency Facilities and Telephone Numbers

Nearest Telephone:			
Fire, Police, Medic Aid Units:	885-3131		
State Patrol:	455-7700		
Hospitals:			
Evergreen General Hospital	821-1111		
Overlake Hospital	454-4011		
Emergency Routes: (See Attachment 1 map to hospitals)			
Emergency Contacts:			
Harborview Hospital, Seattle	223-3005		
EPA-ERT Emergency	321-6660		
EPA Regional Safety Officer (Ron Blair)	442-0370 851-8579		

# Site Description/History of Activities

This facility produces circuit boards and sheet metal products and does electroplating. Materials used include concentrated acids and caustics, solvents, cyanide and several heavy metals including copper, tin, lead and zinc. Past practices included waste discharges to a septic tank and lagoon which is now filled in with a building over the site. There is a high potential threat to groundwater. Wastes are now removed or discharged to METRO sewers.

# Hazardous Substances Suspected On-Site/Assessment

The hazardous substances suspected on-site are heavy metals, cyanide, and chlorinated solvents. Sampling activities will include collection of groundwater and soil borings. Samples are environmental in nature and are not expected to pose a significant health hazard, however, Draeger tube analysis will be done. If Draeger tube analysis shows cyanide contamination, then the site investigation team will leave the site.

# Equipment Lists

# I. Level D

- Tyvek coveralls or rain suits
- Neoprene steel toe and shank boots
- Chemical resistant gloves "Solvex"
- Safety goggles if necessary
- Hard hat
- Latex inner glove liners

# II. Level C

- Air purifying full face respirator (MSHA NIOSH approved)
- Tyvek (Saranex if raining) coveralls
- Gloves (inner), latex chemical resistant
- Gloves (outer), chemical resistant- "Solvex"
- Boots, chemical resistant steel toe and shank
- Hard Hat
- Duct tape

#### Decontamination Procedures

#### I. Level D Decontamination

If soiled, Tyvek coveralls, and gloves will be placed in plastic bags and removed from the site for disposal. Boots will be washed with detergent and rinsed before leaving the site. If rain suits instead of Tyvek coveralls are used, soil will be rinsed off while they are still being worn and before the boots are washed.

#### II. Level C Decontamination

Station 1: Contaminated Equipment Drop

Equipment used on-site (tools, sampling devices and containers, monitoring instruments, radios, clipboards, etc.) will be separated and deposited on plastic drop cloths. Each will be contaminated to a different degree. Segregation at the drop reduces the probability of cross-contamination.

Station 2: Boot and Glove Wash

Scrub boots and gloves with detergent/water solution.

Equipment: container (20-30 gallons)

detergent water

2-3 long-handle, soft-bristle scrub brushes

Station 3: Boot and Glove Rinse

Rinse off detergent solution from Station 2 using copious amounts of water. Repeat as necessary.

Equipment: container (30-50 gallons)

or

pressure spray unit

water

2-3 long-handle, soft-bristle scrub brushes

Station 4: Tape Removal

Remove tape around boots and gloves and deposit in plastic bag or container with plastic liner.

Equipment: plastic bag

or

container (20-30 gallons)

plastic liners

Station 5: Boot Removal

Remove boots, step onto clean dry plastic sheeting.

Station 6: Outer Glove Removal

Remove outer gloves and deposit in plastic bag or container with plastic liner.

Equipment: plastic bag

or

container (20-30 gallons)

plastic liners

Station 7: Coverall Removal

Remove coveralls and deposit in plastic bag or container with plastic liner.

Equipment: plastic bag

OT

container (20-30 gallons)

plastic liners

Station 8: Facepiece Respirator Removal

Remove facepiece. Avoid touching face with gloves. Deposit facepiece in individual plastic bags. Decontaminate off of the site.

Equipment: plastic bags

Station 9: Inner Glove Removal

Remove inner gloves and deposit in a plastic bag or a container with plastic liner.

Equipment: plastic bag or container (20-30 gallons) plastic liners